

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA

Division Director

Minerals Inspection Report

Reviewed

	Report Date	e:								
Mine	Name: Nephi Gypsum Quarry	Permit Number:	M/023/001	1	Mine Status:	Active				
Operator Name: Robert Steele and Tony Peck		Inspection Date:	04/03/2015		Permit Fees:	Paid				
Inspe	ector(s): Wayne Western	Inspection Time:	3:20 - 3:50 Pm		Bond Amount:	\$52,000				
Atter	ndee(s):	Weather:	clear and mild		Bond Escalation:	12/11/2017				
Inspe	ection Purpose: Routine inspection				Prior Inspection:	08/13/2014				
Conclusions and Recommendations In 2014, the Operator reported mining 10,000 tons of material with no new disturbance or reclamation.										
	Elements of Inspection	n		Evalu	ated & Commented	Enforcement				
1.	ermits, Revisions, Transfer, Bonds				\boxtimes					
	Permit fees and bond current									
2.	ublic Safety (shafts, adits, trash, signs, highwalls)		\boxtimes							
	There are warning signs to the mine.									
3.	Protection of Drainages/Erosion Control									
	No sign of erosion problems.									
4.	Deleterious Material									
5.	Roads (maintenance, surfacing, dust control, safety)									
6.	Reclamation									
7.	Backfilling/Grading (trenches, pits, roads, highwalls, share	fts)								
8.	Soils									
9.	Revegetation									
10.	Other									

Inspector's Signature:		
CC:		

 $File: \ /C/Users/WAYNEW \sim 1/App Data/Local/Temp/acrord 32_sbx/A9R9EEE.tmp$



M/023/0011 Mine: Page 2 of 2

Inspected: 04/03/2015



Upper pit. Vegetation on the road to the upper pit suggest that access to this area is limited. Looking at the west area. There are stockpiles of material that are loaded from this site.





East side of quarry. Material has been stockpiled.



Face, looking south.

